

Track too close to copper item

@(1.6370 in, 5.8470 in): Track 0.0208 in [<no net>] on In1.Cu, length: 0.1500 in

@(1.6370 in, 5.6370 in): Pcb Graphic Arc, length 0.2100 in on In1.Cu

Track too close to copper item

@(1.4271 in, 1.3380 in): Track 0.0208 in [/D+] on In1.Cu, length: 4.3000 in

@(1.6370 in, 5.6370 in): Pcb Graphic Arc, length 0.2100 in on In1.Cu

Track too close to copper item

@(1.6370 in, 5.7010 in): Track 0.0208 in [<no net>] on In1.Cu, length: 0.1500 in

@(1.6370 in, 5.6370 in): Pcb Graphic Arc, length 0.0640 in on In1.Cu

Unconnected items

@(1.4271 in, 1.3380 in): Track 0.0208 in [/D+] on In1.Cu, length: 0.6040 in

@(1.8491 in, 1.3390 in): Track 0.0208 in [/D+] on In1.Cu, length: 4.3000 in

Unconnected items

@(2.7011 in, 1.3380 in): Track 0.0208 in [/D+] on In1.Cu, length: 4.3000 in

@(2.2771 in, 1.3410 in): Track 0.0208 in [/D+] on In1.Cu, length: 4.3000 in

Unconnected items

@(5.2601 in, 1.3390 in): Track 0.0208 in [/D+] on In1.Cu, length: 4.3000 in

@(4.8361 in, 1.3420 in): Track 0.0208 in [/D+] on In1.Cu, length: 4.3000 in